

Address / Location	Scoping Results	File Links Maximum upload file size: 100 MB
101,103 Common Line 1 (white pipe) Bogue Court	At 71'4", an 18" pipe is broken and dislodged 1/2". No blockage occurring.	*Video File too Large
101,103 Common Line 2 (black pipe) Bogue Court	Small roots 3' down. Roots blocking most of pipe at 36', can push through, no buildup. Roots blocking left half of pipe at 37', not causing problem. At 37', 1/4" disjoint up, a little still water, no blocks. 54'5" Full block with 1/2" deep standing water.	Photo: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-1-Bogue-Ct-101-103-Common-Line-2-1.jpg *Video File too Large
102 Bogue Court.	Couldn't find	
102,104 Common Line Bogue Court	In woods behind unit. 0' Full blockage. Bad. Unable to push through. Pipe 1/2 full of waste. Waste full block.	Video: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Video-Bogue-Ct-102-104-Common-Line.mp4 Photo 1: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-1-Bogue-Ct-101-103-Common-Line-2.jpg Photo 2: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-2-Bogue-Ct-102-104-Common-Line.jpg
104 Bogue Court.	Couldn't find	
105 Bogue Court.	Clear to sewer	Video: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Video-Bogue-Ct-105.mp4
106 Bogue Court.	A possible 1/4" disjoint in the line was reported at the 17' mark. There are no blockages; water is flowing. Small hanging roots at the 34' & 40' marks.	Photo 1: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-1-Bogue-Ct-106.jpg Photo 2: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-2-Bogue-Ct-106.jpg *Video File too Large
106,108,110 Common Line Bogue Court	Good	Video: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Video-Bogue-Ct-106-110-Common-Line.mp4 Photo: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-1-Bogue-Ct-106-110-Common-Line.jpg
107 #1 Bogue Court.	Clear to sewer	Video: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Video-Bogue-Ct-107-1.mp4
107 #2 Bogue Court.	Clear to sewer	Video: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Video-Bogue-Ct-107-2.mp4
108 Bogue Court.	Couldn't find.	
109 Bogue Court.	Clear to sewer	Video: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Video-Bogue-Ct-109.mp4
110 Bogue Court.	Couldn't find.	
111 Bogue Court.	A 1/4" disjoint in the line was reported at the 6'9" mark; water still flowing - good to sewer.	Photo: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-1-Bogue-Ct-111.jpg *Video File too Large
112 Bogue Court.	Couldn't find.	
113 Bogue Court.	Roots in the line were reported at the 29' mark - blocked pipe and camera. No buildup of waste, and no buildup of water.	Video: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Video-Bogue-Ct-113.mp4 Photo: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-1-Bogue-Ct-113.jpg
114 Bogue Court.	Couldn't find.	
116 Bogue Court.	A 1" belly/drop in the line was reported between the 26' to 31'1" marks, and a 2" belly was reported at the 55'7" mark. Water still flowing.	Photo 1: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-1-Bogue-Ct-116.jpg Photo 2: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-2-Bogue-Ct-116.jpg *Video File too Large
118 Bogue Court.	Clear to sewer	Video: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Video-Bogue-Ct-118.mp4
120 Bogue Court.	Clear to sewer	Video: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Video-Bogue-Ct-120.mp4
122 Bogue Court.	Clear to sewer	Video: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Video-Bogue-Ct-122.mp4
124 Bogue Court.	Clear to sewer	Video: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Video-Bogue-Ct-124.mp4
502 Pebble Creek Dr.	Clear to common line	Photo 1: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-1-Pebble-Creek-Dr-502.jpg Photo 2: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-2-Pebble-Creek-Dr-502.jpg *Video File too Large
504 Pebble Creek Dr.	Clear to common line	Video: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Video-Pebble-Creek-Dr-504.mp4
506 Pebble Creek Dr.	A potential partial 1/8" disjoint was reported at the 62'10" mark. Small roots on top half of pipe at 77'9" NOT causing a blockage.	Photo 1: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-1-Pebble-Creek-Dr-506.jpg Photo 2: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-2-Pebble-Creek-Dr-506.jpg Photo 3: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-3-Pebble-Creek-Dr-506.jpg *Video File too Large

508 Pebble Creek Dr.	A small belly and roots were reported at the 24' mark. A few small roots were found at the joints in the common line starting at the 50'8" mark. No blockage.	<p>Photo 1: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-1-Pebble-Creek-Dr-508.jpg</p> <p>Photo 2: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-2-Pebble-Creek-Dr-508.jpg</p> <p>Photo 3: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-3-Pebble-Creek-Dr-508.jpg</p> <p>Photo 4: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-4-Pebble-Creek-Dr-508.jpg</p> <p>Photo 5: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-5-Pebble-Creek-Dr-508.jpg</p> <p>Photo 6: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-6-Pebble-Creek-Dr-508.jpg</p> <p>Photo 7: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-7-Pebble-Creek-Dr-508.jpg</p> <p>*Video 1 File too Large</p> <p>Video 2: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Video-2-Pebble-Creek-Dr-508.mp4</p>
510,512 Pebble Creek Dr.	A possible 6" break in the top half of the pipe was reported at the 16' mark. Photo shows clump of roots on bottom of pipe. No blockage occurring. Clear to sewer.	<p>Photo 1: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-1-Pebble-Creek-Dr-510-512.jpg</p> <p>Photo 2: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-2-Pebble-Creek-Dr-510-512.jpg</p> <p>Photo 3: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-3-Pebble-Creek-Dr-510-512.jpg</p> <p>Photo 4: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-4-Pebble-Creek-Dr-510-512.jpg</p> <p>Photo 5: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-5-Pebble-Creek-Dr-510-512.jpg</p> <p>Photo 6: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-6-Pebble-Creek-Dr-510-512.jpg</p> <p>Photo 7: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-7-Pebble-Creek-Dr-510-512.jpg</p> <p>*Video File too Large</p>
Common Line 1 Near sewer, Pebble Creek Dr.	Clear to sewer	<p>Photo 1: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-1-Pebble-Creek-Dr-Common-Line-1-2.jpg</p> <p>Photo 2: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-2-Pebble-Creek-Dr-Common-Line-1-2.jpg</p> <p>Photo 3: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-3-Pebble-Creek-Dr-Common-Line-1-2.jpg</p> <p>Photo 4: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-4-Pebble-Creek-Dr-Common-Line-1-2.jpg</p> <p>Photo 5: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-5-Pebble-Creek-Dr-Common-Line-1-2.jpg</p> <p>Photo 6: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-6-Pebble-Creek-Dr-Common-Line-1-2.jpg</p> <p>Photo 7: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-7-Pebble-Creek-Dr-Common-Line-1-2.jpg</p> <p>Photo 8: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-8-Pebble-Creek-Dr-Common-Line-1-2.jpg</p> <p>Photo 9: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Photo-9-Pebble-Creek-Dr-Common-Line-1-2.jpg</p> <p>Video: https://www.grandchestermeadows.com/wp-content/uploads/2019/02/2018_Video-Pebble-Creek-Dr-Common-Line-1-near-sewer.mp4</p> <p>*Video File too Large</p>
Common Line 2 higher up above the sewer, Pebble Creek Dr.	Small roots on top of pipe at 41', 56'11", 61', at 135'. No blocks.	<p>*Video File too Large</p>